Spacecraft Footprints and Ground-Based Instruments

19950329 0400-0600 UT