Spacecraft Footprints and Ground-Based Instruments

19961128 0800-1000 UT