Spacecraft Footprints and Ground-Based Instruments

19970411 0600-0800 UT