Spacecraft Footprints and Ground-Based Instruments

20030126 0800-1000 UT